

SAFETY MANAGEMENT CERTIFICATE

Certificate No:
SMC-993771
DNV GL Id No:
32174
Date of issue:
2017-05-18

Issued under the provisions of the INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA,
1974, as amended
under the authority of the Government of

THE REPUBLIC OF SINGAPORE

by DNV GL

Particulars of Ship

Name of Ship:	APL SINGAPURA
Distinctive Number or Letters:	S6LT3
Port of Registry:	SINGAPORE
Type of Ship ¹ :	Other cargo ship
Gross Tonnage:	151963
IMO Number:	9632002

Particulars of Company²

Company Name:	CMA CGM International Shipping Company Pte Ltd
Company Address:	9 North Buona Vista Drive #14-01 the Metropolis (Tower 1) Singapore 138588 SINGAPORE
Company Identification Number:	5463827

This is to certify:

that the safety management system of the ship has been audited and that it complies with the requirements of the International Management Code for the Safe Operation of Ships and for Pollution Prevention (ISM Code), following verification that the Document of Compliance for the Company is applicable to this type of ship.

This Safety Management Certificate is valid until **2019-02-26**, subject to periodical verification and the validity of the Document of Compliance remaining valid.

Completion date of audit on which this Certificate is based: **2014-02-27**

Issued at **Shanghai, China** on **2017-05-18**



for DNV GL

Shao You Chang
Shao You Chang
Surveyor

¹ Insert the standard IMO ship type.
² See paragraph 1.1.2 of the ISM Code.



Certificate No: **SMC-993771**
Date of issue: **2017-05-18**

Endorsement for periodical verification and additional verification (If required)

THIS IS TO CERTIFY:

that at the periodical verification in accordance with regulation IX/6.1 of the Convention and paragraph 13.8 of the ISM Code, the safety management system was found to comply with the requirements of the ISM Code.



Intermediate Verification³: Place: **Shenzhen, China**

Date: **2017-02-16**

CONFIRMED CARRIED OUT

Signature: *Changshao*

Surveyor, DNV GL

Stamp

Additional Verification⁴: Place: _____

Date: _____

Signature: _____

Surveyor, DNV GL

Stamp

Additional Verification⁴: Place: _____

Date: _____

Signature: _____

Surveyor, DNV GL

Stamp

Additional Verification⁴: Place: _____

Date: _____

Signature: _____

Surveyor, DNV GL

Stamp

³ To be completed between the second and third anniversary dates.

⁴ If applicable. Reference is made to the relevant provisions of section 4.3 "Initial Verification" of the Revised Guidelines on Implementation of the International Safety Management (ISM) Code by Administrations adopted by the Organization by resolution A.1071(28).

W

Certificate No: **SMC-993771**
Date of issue: **2017-05-18**

Endorsement where the renewal verification has been completed and part B 13.13 of the ISM Code applies

The ship complies with the relevant provisions of part B of the ISM Code, and the Certificate should, in accordance with part B 13.13 of the ISM Code, be accepted as valid until:

Place: _____ Date: _____

Signature: _____

Stamp _____ Surveyor, DNV GL

Endorsement to extend the validity of the Certificate until reaching the port of verification where part B 13.12 of the ISM code applies or for a period of grace where part B 13.14 of the ISM code applies

This Certificate should, in accordance with part B 13.12 or part B 13.14 of the ISM Code, be accepted as valid until:

Place: _____ Date: _____

Signature: _____

Stamp _____ Surveyor, DNV GL

msf